## **User Selection Criteria**

Location: NEW YORK
Handler ID: NYD981871726

**Evaluation Date Range:** From: 10/01/1990 To: 02/24/2021

## **Report Results**

Number of Handlers: 1 Number of Pages: 2

## **Report Description**

This report provides a complete listing of evaluation, violation and enforcement activities for each handler, including all orphan records. Below the handler id information, the data is presented in three sections; evaluations, violations and enforcements. Notes are provided in each respective section.

Last Updated On: 01/08/2021

## Comprehensive Compliance Monitoring and Enforcement Report

Page 2

Region: 02

NEW YORK CITY DEP County QUEENS / NY081 NYD981871726

Location 5601 55TH AVE, QUEENS, NY 11378

**Latitud** 40.728682 **Longitude** -73.918862

Mailing: 5601 55TH AVE, QUEENS, NY 11378

Activity N	ſ	State District: NYSDEC R2		Accessibility	Accessibility			Non-		Extract Flag: Y	Active Site: Y	
Generator:	VSG	Operating TSDF:		Offsite R	Offsite Receiver:		State Unaddressed S		essed SNC:	N	EPA Unaddressed SNC:	N
Short Term Generato	r: N	Transporter:	N	IC in Pla	IC in Place:			State Addressed SNC:		N	EPA Addressed SNC:	N
Full Enforcement:		Transfer Facility:	N	El Indica	El Indicator (HE/GW):			State SNC w/Comp Sch		d: N	EPA SNC w/Comp Sched:	N
CA Wrkld:	N	Converter:		HSM:	HSM:		NN					
Active State Gen:	Υ	State TSDF:		Subpart	K:							
CEI Evaluation	07/14/1998	Activity Location:	NY By	/: E	PA Ident	ifier: (	000	Person:	R2MD	Suborganization:	RCB Found Violation	: NO
NOC Date:		Citizen Complaint:	NO Multim	nedia Inspection: I	NO Samp	ling: I	NO	Not Subtitle C:	NO	Day Zero:	Focus Area	:
Eval. Notes:	SITE SCREEN	NED BY CONTRACTOR.	TO BE FOLLOV	VED UP.								

No Linked Violations